

connected only to a short-stroke positioning device, to make fine adjustments in mask orientation and position, or it may simply be fixed.

Please see the attached Appendix for the changes made to effect the above paragraph.